Work Order ID 56997

Tuesday, March 16, 2010 11:41:16 AM



Page 1

Item ID:

D4034-3

Accept

Setup Start

Stop

Revision ID:

Start Date:

Item Name: Rib

Required Date: 3/22/2010

3/16/2010

Start Qty: 5.00 Req'd Qty: 5.00

Operation

Cust Item ID: Customer:

Draw

Number

Reference:

Approvals:

Sequence ID/

Process Plan: MF

Date: 10-3-16 Tooling:

Date:

Start

Reject

Qty

Run

Accept

Qty

Reject

Number

QC:

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Draw

Rev.

Plan

Code

Stop

Insp.

Stamp

Work Center ID Description Draw Nbr Revision Nbr A

D4034

100

Large Fab

Large Fab

Memo

Memo

1- Cut tube as per dwg D4034 2- Drill and chamfer holes as per dwg 0.00

0.00

Sy 10/03/23 5x

110

QC5- Inspect part completeness to step on W/O

8 60103/23

Quality Control

120 Packaging

Packaging

Identify as per dwg & Stock Location:_____

Broket cell

0.00

0.00

SM 10/03/23

Dart Aerosp	ace Ltd	
-------------	---------	--

W/O:			٧	ORK ORDER CHANG	ES					*
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		_								
Part No		PAR #:								
II-	Re	esolution:	Disposit	ion:	_ QA:	N/C CI	sed:		_ Date: _	
NCR:			WORK OR	DER NON-CONFORM	ANCE	(NCR)			1
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description			Sign & V		ation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		Date Section C Chief Er	Section C	Chief Eng	QC Inspector	
										· (0.5)
		ž.		5 4						
										14
										- 6
										1
										1
									Sp.	

Work Order ID 56997

Tuesday, March 16, 2010 11:41:16 AM



Page 2

Item ID:

D4034-3

3/16/2010

QC:

Rib

Setup Start



Revision ID:

Item Name:

Start Date:

Start Qty: 5.00 Req'd Qty: 5.00

Operation

Description

Cust Item ID:

Customer:

Reference:

Approvals:

Required Date: 3/22/2010

Process Plan:

Date: Date:

Tooling:

Accept

Date:

Date:

Run

Start

Stop



Stop

Sequence ID/ Work Center ID

130

Memo

QC21- Final Inspection - Work Order Release

Run Hours

SPC (Y/N):

Set Up/

0.00

Draw Number Draw Plan Rev. Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

Quality Control

0.00

10/03/24 TX)
M/10-3-23

Dart	Aer	osp	ace	Ltd
			~~~	

W/O:			WO	RK ORDER CHANG	ES		Ų.	-		
DATE	STEP	PROCEDURE CHANGE By Date				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									1	
							13			
				V					1	
						1		W.		
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	J. 32	
Resolution:				Disposition: QA: N/C Clos			osed: Date:			
NCR:			WORK ORDE	ER NON-CONFORMA	ANCE (NC	R)				
DATE	STEP	Description of NC		Corrective Action Section B			cation	Approval	Approval	
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector	
				16						
		Tip to								
	le l			it is a second of the second o						
	B . F							100		

## **Picklist Print**

Tuesday, March 16, 2010 11:41:16 AM

Work Order ID: 56997

Parent Item: D4034-3

Parent Item Name: Rib

Comments: IPP RevA: new issue DD 09.11.23 verified by:EC

per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

Start Date: 3/16/2010

Start Qty: 5.00

Required Date: 3/22/2010

Required Qty: 5.00

Component Item ID/ Item Name M304TS0.750W.049

Replacement Mfg/ Item ID Purch

Purchased

Primary Item Location No

Last Location

Route Seq ID 100

Unit of Measure Hand f

Qty on 170.5455

Remaining Qty To Pick 7.5658

Qty Issued

Date Issued

Status

304 SQ Tube .75x.75x.049W

Warehouse Loc Qty Loc Code Location Main Warehouse MAT 170.5455158


106604 2.4123 107460 28.2726 113763 139.860616

7.5658'
END BAR I feet DCRAP

Page 1

Dart Aerosp	pace Ltd
-------------	----------

W/O:			WC	ORK ORDER CHANG	ES					
DATE	STEP	PROCEDURE CHANGE			Ву	Dat	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
					ii e					
						_				
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Ye	s No	DQA:	_ Date: _	)	
Resolution:			Disposition: Q			QA: N/C Closed: Date:				
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NO	CR)				
DATE	STEP	Description of NC	Description of NC		rrective Action Section B			Approval	Approval	
DAIL		Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da	1 &	erification Section C		QC Inspector	
									-	
							14		14	
		ž.								



## **Dart Aerospace Ltd**

	1071								
W/O:			WC	ORK ORDER CHANGE	S		1		
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				4.		-38			
						<u> </u>			F
Part No		PAR #:							4-1
Resolution:			Disposition: QA: N/C Closed: Date:						
NCR:		V	VORK ORDI	ER NON-CONFORMA	NCE (NC	R)		-	1
DATE	STEP	Description of NC		The body of the control of the contr			Approval	Approval	
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sect	Verification Section C	Chief Eng	QC Inspector
					9	15			
3							4		
			-			i,			